

Table 6. Summary of Bank Erosion Potential based on Length of Site as compared to Bank Height along Black Hole Creek\*

Summer2003\*\*

### Total Banks

<b>LENGTH IN FEET</b>	<b>0-50</b>	<b>51-100</b>	<b>101-250</b>	<b>251-500</b>
Low Bank Height	41	3	4	2
Moderate Bank Height	23	2	1	2
High Bank Height	12	6	2	0
<b>Total</b>	<b>76</b>	<b>11</b>	<b>7</b>	<b>4</b>
<b>Percent of 98</b>	<b>77.55%</b>	<b>11.22%</b>	<b>7.14%</b>	<b>4.08%</b>

### Right Banks

<b>LENGTH IN FEET</b>	<b>0-50</b>	<b>51-100</b>	<b>101-250</b>	<b>251-500</b>
Low Bank Height	18	3	2	1
Moderate Bank Height	12	0	1	1
High Bank Height	6	3	1	0
<b>Total</b>	<b>36</b>	<b>6</b>	<b>4</b>	<b>2</b>
<b>Percent of 48</b>	<b>75.00%</b>	<b>12.50%</b>	<b>8.33%</b>	<b>4.17%</b>

### Left Banks

<b>LENGTH IN FEET</b>	<b>0-50</b>	<b>51-100</b>	<b>101-250</b>	<b>251-500</b>
Low Bank Height	23	0	2	1
Moderate Bank Height	11	2	0	1
High Bank Height	6	3	1	0
<b>Total</b>	<b>40</b>	<b>5</b>	<b>3</b>	<b>2</b>
<b>Percent of 50</b>	<b>80.00%</b>	<b>10.00%</b>	<b>6.00%</b>	<b>4.00%</b>

\*Study Area All of Black Hole Creek

\*\* Completed by Lycoming College Clean Water Institute Interns

[Back to CWI Reports](#)